
CITY OF BALTIMORE WET SMOKE AND DYED I	Page 1 of 3								
Sewershed: Low Level Subsewershed: 44	Company: REI/DRAYCO	Date: 09/02/2008 Supervisor: E.R. Crew: 04							
Test Type: Smoke	Ground Condition: Dry: X Damp:_ Wet:_								
Manhole ID: S17M025MH	Test ID: 1029-585	Notifications Made:X Residents, Fire, 311							
Field Sketch: (Show all manholes with numbers, blower placement location, sandbag or isolation locations, street names, building addresses									

and locations, defect locations and photograph numbers)



CITY OF BALTIMORE WET WEATHER CONSENT DECREE SMOKE AND DYED WATER TESTING FORM						Page 2 of 3					
ţ	Sewershed: Low Level Subsewershed: 44	Company: REI/DRAYCO					Date: 09/02/2008				
	Test Type: Smoke Ground Condition: Dry: X Damp:_ Wet:_							Supervisor: E.R. Crew: 04			
	nhole ID: S17M025MH	Test ID: 1029-585				Notifications Made:X Residents, Fire, 311					
Field Sketch: (Show all manholes with numbers, blower placement location, sandbag or isolation locations, street names, building addresses and locations, defect locations and photograph numbers)											
Defect No.		Source Type			Sector	Drai	nage rea			Photo Number	
1	400 MILLINGTON AVE.	03	14		02		1	03		1029-585_OB01-01.jpg	l
						<u> </u>					
			1			-					
						 					
		OB			ION CO	DES	_				
	Source Type		Locat					Sector		Severity	
	ain Sewer 10 MH Frame	01 Paved 0						Public		No Smoke	
	ervice Line 11 Storm Drain	02 Asphalt			Field/W	oods	02	Private		Trace	
	eanout 12 Catch Basin ownspout 13 Storm MH	03 Paved 0				urca				Moderate	
	ownspout 13 Storm MH ea Drain 14 Storm Ditch	04 Drivewa 05 Sidewal			Golf Co Other	urse			υ4	Major	
	vy. Drain 15 Excavation	06 Curb	r.	14	Other						
	air. Drain 16 Water Line	00 Cuib 07 Yard - F	ront								
	ound. Drail 17 Tele. Pole	08 Yard - E									
	dg. Interio 18 Other	09 Yard - S									

PAGE 3 of 3

CITY OF BALTIMORE SMOKE TESTING OBSERVATION SUMMARY LOW LEVEL SEWERSHED

BALTIMORE CITY PROJECT 1029 REI/DRAYCO

Unique Test ID: 585 Date: 09/02/2008 Basin: LL - 44 Manhole ID: S17M_025MH
Defect No: OB01 Supervisor: E.R. Crew: 04 Dye Test Recommended: N

Location: 400 MILLINGTON AVE.

Source Type: 03 Cleanout Sector: 02 Private

Location: 14 Other Severity: 03 Moderate Drainage Area: 1

Comments: ABOVE GRADE CLEANOUT WITHOUT CAP IN FLOWER BED.

SMOKE TEST PHOTOGRAPHS



Photograph No: OB01-01 Filename: 1029-585_OB01-01.jpg